

Aurecon New Zealand Limited T +64 3 366 0821
Unit 1 F +64 3 379 6955
150 Cavendish Road E christchurch@ap.aurecongroup.com
PO Box 1061 W aurecongroup.com
Christchurch 8140
New Zealand



15 February 2016

CDL Land New Zealand Limited
PO Box 3248
Auckland 1140
Via E-mail

Attention: Mr. Jason Adams

Dear Jason

Post-earthquake inspection Prestons Park: Sub-stages M and N

Aurecon engineering staff completed an inspection of visible infrastructure and surface earthworks within substages M and N following the Christchurch 5.7 magnitude earthquake experienced 14/02/2016.

The inspection included review of completed footpaths, kerb and channel, carriageway, manholes and valve chambers visible from the surface. There was no visible damage as a result of seismic movement observed in these civil elements within substages M and N. The gravel embankments, culvert headwall structures and finished lots were also inspected however there was no evidence found of any differential movement or lateral spread in these areas. There was also no visible evidence of liquefaction on the surface within these substages.

Yours faithfully

A handwritten signature in blue ink, appearing to read "jeanette".

Jeanette White
Civil Engineer Land Infrastructure