

Aurecon New Zealand Limited T +64 3 366 0821
Unit 1 F +64 3 379 6955
150 Cavendish Road E christchurch@ap.aurecongroup.com
PO Box 1061 W aurecongroup.com
Christchurch 8140
New Zealand



14 November 2016

CDL Land New Zealand Limited
PO Box 3248
Auckland 1140
Via E-mail

Attention: Mr. Jason Adams

Dear Jason

Post-earthquake inspection Prestons Park: Civils Stage 1

Aurecon engineering staff completed an inspection of visible infrastructure and surface earthworks within Stage 1 following the North Canterbury 7.5 magnitude earthquake experienced 14/11/2016. During the inspection particular attention was paid to substage P where Practical Completion has been reached by the Contractor however the stage has not yet been vested with Council.

The inspection included review of completed footpaths, kerb and channel, carriageway, manholes and valve chambers visible from the surface. There was no visible damage as a result of seismic movement observed in these civil elements. The gravel embankments, culvert headwall structures and finished lots were also inspected however there was no evidence found of any differential movement or lateral spread in these areas. There was also no visible evidence of liquefaction on the surface within these substages.

Yours faithfully

A handwritten signature in blue ink, appearing to read "J. Tucker".

Jeanette Tucker
Civil Engineer Land Infrastructure