STATEMENT OF SUITABILITY OF EARTH FILL FOR RESIDENTIAL DEVELOPMENT

To Selwyn District Council PO Box 90 Rolleston 7643

STATEMENT OF SUITABILITY OF EARTH FILL FOR RESIDENTIAL DEVELOPMENT

Subdivision

CDL - Stonebrook, Rolleston - Stage 9, 10 and 11

Owner / Developer

CDL Land New Zealand Ltd

Location

Stonebrook Drive, Rolleston

The earth filling, with depths of fill are shown on the attached plan 224926-DW-LD-S8-12-AB-FC-01 [A], have been place in compliance with the terms of NZS 4431:1989.

While work was in progress I, Ian McPherson c/- Aurecon NZ Ltd, P O Box 1061, Christchurch, acted as consulting Geotechnical Engineer.

During the work, the inspecting engineer and his staff made periodic visits of inspection to the site. Details of the soil testing carried out to check the quality of the fill by the inspecting engineer can be made available upon request.

The attached plan, 224926-DW-LD-S8-12-AB-FC-01 [A], shows those lots affected by filling and the extent of the fill as part of the development works.

In the opinion of the inspecting engineer the following special limitations should be observed:

Nil

This certification, that the earth fills have been placed in compliance with the terms of NZS 4431:1989 does not remove the necessity for the normal inspection and design of foundations as would be made in natural ground.

Somethorson (signature)

Technical Director (position)

13 | 11 | 14 (date)

On behalf of CDL Land New Zealand Ltd



STATEMENT OF SUITABILITY OF EARTH FILL FOR RESIDENTIAL DEVELOPMENT

To Selwyn District Council PO Box 90 Rolleston 7643

(name and address of Local Authority)

STATEMENT OF SUITABILITY OF EARTH FILL FOR RESIDENTIAL DEVELOPMENT

Subdivision

CDL - Stonebrook, Rolleston - Stages 1 - 3

Owner / Developer

CDL Land New Zealand Ltd

Location

Stonebrook Drive, Rolleston

The earth filling, with depths of fill are shown on the attached plan 224926-DW-LD-EW-CF-01-B, have been place in compliance with the terms of NZS 4431.

While work was in progress I, Dr Jan Kupec c/- Aurecon NZ Ltd, P O Box 1061, Christchurch, acted as consulting Geotechnical Engineer.

During the work, the inspecting engineer and his staff made periodic visits of inspection to the site. Details of the soil testing carried out to check the quality of the fill by the inspecting engineer and his testing agency are also included.

The attached plan, 224926-DW-LD-EW-CF-01-B, shows those Lots affected by filling and the extent of the fill as part of the development works.

In the opinion of the inspecting engineer the following special limitations should be observed:

Nil

This certification, that the earth fills have been placed in compliance with the terms of NZS 4431 does not remove the necessity for the normal inspection and design of foundations as would be made in natural ground.

Molar — (signature)

25/6/2013 (date)

On behalf of CDL Land New Zealand Ltd (name of owner/developer)